

Flytec Balloon 6040

Notes de mise à jour du logiciel

V 3.08b de 25/06/2021

- Correction d'un bug où, dans certains cas, l'affichage du nom du pilote dans le menu et dans les fichiers IGC était écrasé (introduit avec la 3.08a).

V 3.08a de 12/06/2020

- Correction de la perte de réception GPS après 1-3 heures, causée par un bug dans le logiciel du module GPS (IT430 et SE880).
- Réduction du stockage à un maximum de 10 routes (était 20) et 20 balises par route (était 30).

V 3.07a de 12/06/2020

- Amélioration de la réception TT34, filtrage des transmissions incorrectes.

V 3.06c de 12/03/2020

- Reconnaît le module GPS Telit Jupiter SE880.
- Amélioration de la récupération après une perte de réception GPS.
- Protection améliorée contre l'installation de logiciels pour un autre appareil de la même famille.
- Correction d'un bogue où des noms de fichiers erronés pouvaient apparaître dans les listes de fichiers de la carte SD.

V 3.06b de 11/06/2019

- Correction d'un bug dans l'enregistrement du vol qui pouvait empêcher la sauvegarde des données lorsque la réception GPS était mauvaise ou manquante.
- Courbes de charge de batterie améliorées pour une indication plus précise du niveau de charge.
- Nouvelle option de batterie : Eneloop Pro 2500 mAh, batteries NiMH rechargeables.

V 3.05c de 29/03/2019

- Correction d'un bug dans la gestion du changement de date GPS qui pouvait conduire à déplacer la date à 2038.
- Lorsque l'affichage des fichiers des waypoints et des espaces aériens sur la carte SD, supprime les nouveaux fichiers système OS X.

V 3.05b de 18/03/2019

- Dans de rares cas, après une mise à jour, l'écran apparaît tourné de 90° et avec un contraste très faible. Maintenant, l'écran peut être correctement aligné avec la combinaison de touches "Flèche à droite" et "Flèche vers le bas" directement après le démarrage, pendant la confirmation de la langue.

V 3.05a de 03/03/2019

- Corrige les effets du changement de date GPS, le vario donne les dates correctes jusqu'en 2038 au moins

V 3.04b de 16/01/2019

Cette mise à jour supprimera tous les waypoints et routes du vario. Assurez-vous de les enregistrer sur la carte SD ou sur votre ordinateur avant de procéder à la mise à jour.

- La date IGC est désormais également correcte pour les vols commençant entre 00h00 et 0h05 UTC
- Les routes et les waypoints peuvent encore être appelés "A"
- Fichier IGC: le nom du champ pour la date est maintenant conforme à la spécification de fichier IGC 2016
- Correction d'un bug où dans certains cas la première position enregistrée dans le fichier IGC était complètement fausse
- Nouveau mode Bluetooth NMEA 5 (Ozi Explorer), qui alterne entre GPRMC et GPGGA

V 3.03d de 29/03/2018

- Champ de données FL: aligne à droite
- Supprimer les caractères Umlaut des menus allemands
- Corrige le formatage du numéro de série du TT34
- Indique distance correcte lors de l'édition de la route de course

V 3.03c de 15/02/2018

- Correction d'un bug où dans certains cas, l'affichage est devenu illisible après la mise à jour

V 3.03b de 02/02/2018

- Renommé « Paramétrage vario » à « Paramétrage d'appareil »

V 3.03a (2018-01-23)

Cette mise à jour supprimera tous les waypoints et routes du vario. Assurez-vous de les enregistrer sur la carte SD ou sur votre ordinateur avant de procéder à la mise à jour.

- Des écrans de démarrage et d'arrêt plus propres
- Textes mis à jour et unifiés pour les menus et les paramètres de toute la famille vario 6000
- Le lien au fichier d'espace aérien FAF sur la carte SD est supprimé chaque fois que les espaces aériens sont téléchargés de l'ordinateur, ou lorsque les espaces aériens sont supprimés via le menu
- Toutes les valeurs numériques (rayon du cylindre, par exemple) peuvent être augmentées / diminuées rapidement avec les touches fléchées droite / gauche, et plus lentes, pour des réglages plus fins, avec les touches fléchées haut / bas
- Les distances dans les routes sont affichées avec une décimale
- Gamme de correction du capteur de vitesse externe: 50% à 150%
- Dans le fichier IGC, les enregistrements C «takeoff» et «landing» sont maintenant réglés conformément à la spécification

V 3.02a (2018-01-04)

- Correction d'un bug, le téléchargement d'espaces aériens ne cause plus une réinitialisation avec de mauvaises valeurs (par exemple, numéro de série 500)

V 3.01a (2017-10-27)

- Améliore la réception des données de TT34, filtrer les valeurs irréalistes
- Ecran de démarrage plus propre

V 3.00a (2017-08-09)

- Correction de la configuration de base pour varios avec numéro de série 6649 et suivantes
- Champs de données: correction de certains noms de champs
- Champ de données "FL (ft)" renommé en "Alt FL", maintenant à 3 chiffres, en hecto-pieds selon la norme

Le notes plus anciens sont disponibles qu'en Anglais au moment.

V 2.07i from 30/10/2013

Attention! With version 2.07b the flight memory will be deleted, since a new flight memory organization was needed. Furthermore, it is a log file will be written on SD card to track possible errors better. We therefore recommend operating the instrument only with an SD card from version 2.07 on.

- Bugfixes and improvements in temperature warning
- Wrong TT34 SN. The detection has been improved.
- ? - ? Now also in large data fields.
- Airspaces from SD card. So *.faf file format from Flyland or OpenAir data from around the world can be loaded directly to the SD card with all the additional information. The instrument takes the nearest 100 air spaces for the calculation of the approximation warnings.
- New flight memory organization. This means that all flights will be deleted in the flight memory with this update.
- External RAM used now
- Revision CTR / error page
- Log file with status and error messages on the SD card
- Recognition of the new GPS module IT430 .
- Settings can be saved to SD card and read back again .

V 2.06i from 22/11/2012

- Storing a new TT34 ID with F2 key. This is the automatic search function for the TT34
- Doubling the clock frequency with different timing adjustments
- Bug fix of suddenly occurring altitude jumps (whine of the Vario).
-

V 2.06 from 25/02/2011

- New: Rise acoustic. It can be switched on or off in -> Main Setup Menu -> Settings -> Variometer -> Customize sound -> Rise acoustic -> Yes/No.
- New NMEA sentence \$FLYSEN via Bluetooth. All internal sensor values can be read out and used in computer navigation programs as well as in automatic burner controls.

V 2.05z from 18/8/2010

- Initialization for new lot Fastrax changed

V 2.05y from 8/6/2010

- Bugfix freezing of display during NMEA Output via Bluetooth

2.05x from 26/4/2010

- New Menu SD-Card
- Export of flights on SD Card. The SD Card must be formatted with FAT or FAT 16. Therefore maximum size is 2GB.
- Export and import of waypoints and routes on SD card in format *.gpx.

V 2.05w2 from 7/1/2010

- Bugfix NMEA via Bluetooth. Freezing after pairing fixed.
- Temperature alarm minimum from 70°C reduced to 40°C

V 2.05t from 11/11/2009

- Info page in the vario and windlayer screen lists the pending alarms, the info page in the map screen lists the nearest CTR's
- Bugfix in the CTR list. Wrong CTRs in the list (far away but with distance 0) could be eliminated.
- Bearing arrow bigger
- New handling of the compass rose.
Empty compass rose with active bearing arrow showing towards up direction in case of no GPS reception. The bearing arrow should show, that a waypoint or route is active.
Compass rose north up and active bearing also north up in case of GPS speed below 3 km/h.
- The second and third CTR in the list would be checked every 20 s and 40 s. All other CTR are checked one after each other, one per second.
- CTR acoustic Alarm active/not active. After the firmware update the CTR acoustic alarm is switched off by default. You can set it with -> *Main Setup Menu -> Pilot settings -> CTR acoustic Alarm*
- GPS-Module Type in Startup screen
- Automatic switch off if the instrument has no flight recognition after 30 min. or if the flight analysis screen stays for more than 30 minutes.
- Improvement in memory handling (freezing after start)
- Negative MaxA1 und MaxA2 on the flight analysis screen
- Altitude history ignored after start recognition. This should address the excess values of the vario in the flight analysis.
- Improvements in SMS handling: In the Info page it is possible to send an SMS on demand if an connection to a telephone provider is established. Attention. It is not ensured that an SMS is received by the intended receiver, because it can get lost in the network.

V 2.05r from 28/08/2009

- Cosmetics on teh alarm page

V 2.05o from 15/08/2009

- New Alarm concept
- Temperatur user alarm: New double peeb every 10 s. Can be switched on/off in Main setup menu -> Settings -> Temp Alarm. This alarm can be acknowledged with the Ok button.
- Manufacturer Temp Alarm 130°C: New double beep every 5 s. Info Page appears for 10 s. This alarm cannot be acknowledged.
- Altitude Alarme High or low: Only 1 alarm beep, Altitude inverse

- Wrong ID only Symbol ?--? in Userfield Env. Temp.
- Sensor problem: Only 1 alarm beep and sign -// in Userfield Env. Temp
- No TT34 reception: Only 1 alarm beep and sign -- in Userfield Env. Temp- TT34 reception quality bar empty.
- Info page with info button lists always all pending alarms.

V 2.05i from 19/06/2009

- Fastrax with SiRF protocol. FLARM Timing not yet implemented
- Bugfix freeze after CTR and Bluetooth settings

V 2.05f from 11/05/2009

- Identification string changed to 6040 without total reset.

V 2.05d from 28/04/2009

- Identification string changed to 6040. **Caution:** This will cause a total reset of instruments with earlier versions. Everything except the calibration data will be reset, incl. serial number and company.
- Bugfix Scale in Map in flight book
- New default settings for LCD
- Package 02, 300 CTRs released
- Speed > 100 without decimal

V 2.05b from 8/04/2009

- Barometric altitude in IGC file based on 1013.25 (QNE)
- Zoom and Scroll in windlayer page also in feet scale. Attention after changing the units to feet the instrument needs a restart.

V 2.05a from 7/04/2009

- Refresh ALT1 and QNH also on windlayer and map page.
- Zoom and Scroll on wind layers.

V 2.05 from 1/04/2009

- Bluetooth SPP passive pairing (not tested)
- Bug Fix Grounspeed on wind layer page
- Windlayerpage: Speed > 65 as number
- PEV and change Alt1 during recording released
- New function of Softkeys F1/F2 in map screen
- Text changes

V 2.04a from 11/03/2009

- Namings: Total Alt Upper Alt and Lower Alt, Env Temp, TT34 Serial number, Alt1
- Units added in Temp Alarm Setting
- Temp alarm F1, F2 key eliminated
- Altitude limit (Alt alarm key) also in feet
- No Alt Alarm Settings in the simulation mode

V 2.04 from 026/02/2009

- The problem with two TT34 transmitting in a time slot smaller than 0.5s could be solved.
- Windlayer page also in feet

V 2.03f from 09/02/2009

- Max. manufacturer Env. Temperatur Setting new in the Factory Settings.

- Additional Env. Temp. Alarm User Setting in the instrument settings
- Varointegrator fix on 1 s. Only one Variometer menu topic.
- Acoustic settings only Sinktone and Modulation.
- Hello and goodbye in the chosen language.
- Instrument Setup topic order changed.
- Varioscale on the windlayer page new in ft/min*100
- Units on the varioscale.
- Windlayer graphics shifted to fit better on the page
- Windlayer graphics in mph and kn
- Units of the sink tone alarm in 10ft/min*100 steps.
- New Userfield "QNH inHg" in 1/100 inHg.
- Speed in 0.1km/h resolution
- In Simulation Mode the max. Env. Temp not directly settable with F1/F2
- Sensor break delayed by 1 minute.
- Smoothing Factor and Filter Factor of the GPS module new on 1 (Before 2) Speed and course should be updated faster.
- The problem with two TT34 transmitting in a time slot smaller than 0.5s could not be solved because of an internal timing problem.

V 2.03b from 23/12/2008

- New Errorpage

V 2.03a from 18/12/2008

- -- in Speeddisplay in case of no GPS reception

V 2.03 from 5/12/2008

- Basic version